


# REFERENTIE from Van Hove Nurseries Zaffelare - Belgium



Aquasonic NT4.1 units were placed in the underground tanks and in the irrigation reservoir. Two days after installing the Aquasonic all algae had died and after a rainstorm, the algae sunk to the bottom of the reservoir



Previously the filter screen box needed cleaning 3 times a day. Now it needs cleaning once a fortnight



As a result of the biofilms in the underground tanks disappearing, and the bacteria being killed, improvement in root growth of all nursery plants is obvious after 1 week



Before installing the Aquasonic NT4.1, the floor was very slippery with algae



After a few weeks: there is no algae on the floor; the floor is no longer slippery, it does not need cleaning and dries out much quicker

